

**SSM 49200 - 2018-2019 EcoSport - 1.0L EcoBoost Engine Built On Or Before 3-Apr-2019 - 6F15 - Illuminated Engine Oil Warning Lamp With Loss Of Engine Oil Pressure**

Some 2018-2019 EcoSport vehicles equipped with a 1.0L EcoBoost with an engine build date on or before 3-Apr-2019 and a 6F15 automatic transmission may exhibit an illuminated oil pressure warning lamp with a loss of engine oil pressure. This may be due to an engine oil pump belt tensioner which leads to a loss of engine oil pressure. Due to the nature of this failure, an engine replacement may be required. Engines built after 3-Apr-2019 should not be affected.

APPLICABLE VEHICLES  
2018 - 2019 CAR: BW B515A ECOSPORT INDIA